To: Matt Francis[m.francis@erllc.com]; Bob Heeter[bheeter@harwest.com]
Cc: Chris Hassel[CHassel@harwest.com]; Way, Steven[way.steven@epa.gov]

From: Christoph Goss

Sent: Wed 9/9/2015 4:43:37 PM **Subject:** RE: Gold King Shotcrete

Hi Bob

Please also note that there is no need for accelerator in the shotcrete for the portal support.

Christoph


From: Matt Francis [mailto:m.francis@erllc.com] Sent: Wednesday, September 09, 2015 10:28 AM

To: Bob Heeter bheeter@harwest.com; Christoph Goss christoph.goss@deereault.com>

Cc: Chris Hassel < CHassel@harwest.com>; Steven Way < Way. Steven@epa.gov>

Subject: Gold King Shotcrete

There seems to be some delay in getting the shotcrete spec finalized and approved. EPA/ER being in the middle of these discussions doesn't seem to be the most efficient means of resolving. This needs to be resolved today to match the significant progress being made on site by the work crew. Please communicate directly and respond with the results.



Thank You

Matt Francis

Environmental Restoration, LLC

303.994.6611

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.